


apparent missing flight path information relating to aircraft overflights identified by you; and

3. As a result of the meeting, Airservices understands that the location of the portable aircraft noise monitor at the social club is not considered appropriate and that you and Mr Ray would approach the Diggers Rest Primary School to seek their agreement to install a portable noise monitor at the school. Once agreement has been obtained from the school authorities, Airservices will arrange the installation of the noise monitor as soon as practicable.

I will advise you of the results of the above actions as soon as they are completed.

During the meeting you also asked if you could continue to request and receive information from Airservices' Noise Enquiry Unit (NEU), including information from the NFPMS. I wish to confirm that, as I advised at the time, you are free to request, and will receive, information from the NEU.

Yours sincerely



Richard Dudley
General Manager
Corporate Affairs

17. February 2009